## THE ELECTRIC MATERIALS CO.

MANUFACTURERS C E

BOX 390 NORTH EAST, PA 16428 (814) 725-9621

Toll Free Number (800) 356-2211 Telex 387783 Fax (814) 725-3620

December 15, 1994

Mr. John R. Crow
Solid Waste Specialist
Bureau of Waste Management
Commonwealth of Pennsylvania
Department of Environmental Resources
1012 Water Street
Meadville PA 16335

Subject: Inspection Report Compliance

Dear Mr. Crow:

The content of this correspondence is to answer the comments of your inspection report of November 2, 1994.

- 1. Batch neutralization of acid pickling waste water is not classified by Permit by Rule status, will no longer be reported on the annual report.
- 2. Form 25 R's, sent to Mr. Brian Mummert:
  - Foundry Sand (R101)
  - Wheelabrator Dust (R101)
  - Metal Hydroxide (R101)
  - Cyanide Treatment Waste Water (R403)
  - Draw Lube (R900)
- 3. Waste storage tanks were checked to ensure that waste were not being stored in improper tanks. Labeling for each tank is correct and the tanks are also labeled as to which tanks are used to store hazardous materials.

CEL SOLUTO

# NRO

#### THE ELECTRIC MATERIALS CO.

Mr. John R. Crow
Solid Waste Specialist
Bureau of Waste Management
Commonwealth of Pennsylvania
Department of Environmental Resources
Meadville PA 16335
Page 2
December 15, 1994

- 4. At the present time the hazardous waste storage areas are monitored days by the attendant; second and third shift by plant security. To ensure this, written forms have been developed to document this security. A copy of the form is enclosed.
- 5. Status Quo.
- 6. Training of employees handling hazardous waste as stated in the regulations will be followed and a copy of the documentation sheet is enclosed.
- 7. Accurate reporting of waste volumes and weights will be noted on all Quarterly Reports.
- 8. The Preparedness, Prevention and Contingency Plan (PPC Plan) has been revised as requested and a copy is enclosed. Also enclosed is a report and corrective actions taken on the cyanide spill incident.

Hopefully, this information sufficiently satisfies the request of the report. If additional information is required, please contact me at 814-725-9621 ext. 297.

Sincerely,

THE ELECTRIC MATERIALS COMPANY

John Wilcox

John Wilex

Safety & Environmental Manager

JW/pc

Encl.

# COMMONWEALTH OF PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL RESOURCES BUREAU OF WASTE MANAGEMENT

# HAZARDOUS WASTE INSPECTION REPORT GENERATORS - PART A

Date of Inspection	11-2-94 Tim	e start <u>9:00</u>	Time finish 17	2:10
Name of Inspector	Joh	on Crow		
Company, installation n	name "The "Flec	tric Mate	erials Co.	
Location 50 Soc	th Washington	St. Nort	h East PA. 16	5428
CountyE	Prie	Municipality	North East	
Identification number_	PAD0050	28642		
Name of responsible of	ficial <u>mr</u>	John (e)	ilcox	
Title	Safety	Director		
Mailing Address 50	South lebashing	aton St. No	orth East PA	16438
	ne number <u>814</u>			
	ewedMr.			
Title	Safety	Director		
Mailing address (if diffe	erent from above)	above		
Area code and telephor	ne number	above		W
Current waste han	dling method:			
a. 🗖 On-site	☐ treatment,	storage,	☐ disposal	<b>⊠</b> PBR
b. 🔀 On-site	use,	☐ reuse,	☐ recycle,	<b>⊠</b> reclaim
c. 🔀 Off-site	☑ treatment,	☐ storage,	☑ disposal	
d. 🔀 Off-site	use,	□ reuse,	☐ recycle,	<b>⊠</b> reclaim
3 Amount of house		_	_ ,	_
<ol><li>Amount of hazard</li><li>a.</li></ol>	ous waste produced:  ~ 92,027	ka/ma Dosa	f on 1992-1994 man	fats ander to
b. ~ 1			d annual PBR repo	
<b>U</b> .	;107,0a1	Kg./yr.	1	•
3. Types of hazardo location and type)	us waste produced by H	azardous Waste	Number and destination	n facility (include
Tocation and type)	•			
Waste Number	Destination Fa	icility	Location and	Туре
DOII	RFE Ind. Inc. Foo	ot of Jerseuf	ve. Jersey City. N.	T 07303
D003 D006 D008	Environmental Ent. 465	_ '	1	
Dogi	Chemical Solvents In	c. 7010 Denison	Ave. Cleveland Of	F0144
F002	Ecolotec Inc. 716	N. Irwin St.	Douton OH 454	104
E003	Marine Shale Proce		Morgan City Lo	70389
10040. F00i	Chemtron Corp. 35		<b></b>	14011
FOOI, DOYO	Safety-tileen 37100			40050
DOD2, FOOT 4. Source Reduction:	Cyanakem 12381 S accomplished, prop	chaefar Highwa	4. Detroit, MI L	18227

ER-WM-300: Rev. 11/93 Part B

# COMMONWEALTH OF PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL RESOURCES BUREAU OF WASTE MANAGEMENT

# HAZARDOUS WASTE INSPECTION REPORT GENERATORS - PART B

Site Name The Electric Materials Co. ID Number PADO05028642 Date 11-2-94

## Hazardous Waste Inspection Report Generators - Part B

1-No Violation Observed 2-Not-Applicable 3-Not-Determined 4-Non-Compliance

	STA	TUS			CHAPTER CHAPTER	LINE
1	2	3	4	REQUIREMENT	CITATION	ITEM
$\setminus$				Hazardous waste determination, performed on all waste streams	262.11	H001
<				Identification number	262.12	H002
${\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ $				Hazardous waste shipments offered only to licensed transporters	262.12(d)	H003
				Authorization received from TSD facility for wastes shipped off-site within PA	262.13	H004
$\overline{\ }$				PA manifest used for intrastate shipments	262.20(b)	H005
<				TSD state manifest or PA manifest used for out-of-state shipments	262.20(c)	н006
$\setminus$				Manifests filled out properly and completely	262.20(g)	H007
$\checkmark$				Manifests routed properly and within time limits (7 days)	262.23(e)(f)	H008
$\setminus$				Proper U.S. DOT shipping containers or packages being used	262.30(1)	H009
$\sqrt{}$				Shipping containers marked and labeled according according to U.S. DOT	262.30(2)	H010
$\checkmark$				Containers of 110 gal. or less permanently marked with required hazardous waste label	262.30(3)	H011
$\setminus$				Placards offered to transporter	262.33	H012
				Waste in containers or tanks accumulated on-site for less than 90 days	262.34(a)(1)	H013
				Wastes placed in containers properly marked and labeled or in tanks meeting requirements of Chapter 265, Subchapter J. SEE Comment *3	262.34(a)(2)	H014
				Containers managed in accordance with Chapter 265, Subchapter I (any non-compliance for Subchapter I requirements is a violation of 262.34(a)(3))	262.34(a)(3)	H015
$\overline{\ \ }$				a). All containers of haz. waste in good condition	265.171	H016
				b). Containers compatible with hazardous waste being stored within	265.172	H017
				c). Containers of hazardous waste kept closed	265.173(a)	H018
				d). Containers of hazardous waste are managed to prevent leaks	265.173(b)	H019
1				e). Containers of hazardous waste labelled to accurately identify contents	265.173(c)	H020
×				f). Haz. waste accumulation areas inspected at least weekly SEE Comment #	265.174	H021
/				g). Special requirements for ignitable, reactive and incompatible waste being met	265.176177	H022
/				h). Proper containment and collection system(s)	265.178	H023
				Containers clearly marked with accumulation date and visible for inspection	262.34(a)(4)	H024
~			X	On the job or classroom personnel training program as per 265.16 ** 6	262.34(a)(5)	H025

#### Hazardous Waste Inspection Report Generators - Part B

1-No Violation Observed 2-Not-Applicable 3-Not-Determined 4-Non-Compliance

	STA	TUS	5	DECUMPENT	CHAPTER	LINE
1	2	3	4	REQUIREMENT	CITATION	ITEM
$\mathcal{J}$				Records retained at designated location for 20 years	262.40(a)	H026
7				Quarterly reports submitted to the Department Sectorment # 7	262.41(a)	H027
Ī	1			Exception reporting procedures followed	262.42	H028
	$\Box$	1		Hazardous waste disposal plan, if required	262.45	H029
				Spill reporting procedures followed	262.46(a)	H030
		1		Preparedness, Prevention and Contingency Plan developed and implemented in accordance with Chapters 264 and 265 SEE Comment # 8	262.46(e)	H031
	/			Special requirements followed for international shipments	262.50,.53, .55, .60	H032
			X	Source reduction strategy prepared and available at comment # a	262.80	H033

#### Pennsylvania Department of Environmental Resources Bureau of Waste Management

## Hazardous Waste Inspection Report Land Disposal Restriction Supplemental Checklist

			1-No	Violation Observed 2-Not Applicable 3-Not Determined 4-Non-	Compliance								
1	Sta	itus	4	REQUIREMENT	Citation 40 CFR								
	2	-	-	Generators	Part 268								
7		-	-	Notification sent with shipments of wastes that do not meet treatment standards.	7(a)(1)								
<del>/</del> /	-	+	-	Notification and certification sent with shipments of wastes meeting treatment standards.	7(a)(2)								
\ ./	-	-	$\vdash$	Dilution not used as a substitute for treatment.	3								
<u>\</u>		-		Records maintained of notifications, certifications, waste analysis, and documentation supporting use of knowledge for waste classification.									
				Storage Facilities									
				Facility verifies generators classification of waste in accordence with waste analysis plan.									
	W			Containers marked to identify contents and accumulation date.	50(a)(2)								
	X			Notification sent with shipments of wastes that do not meet treatment standards.	7(a)(1)								
	1/1			Notification and certification sent with shipments of wastes meeting treatment standards	7(a)(2)								
	$I \setminus I$			Facility maintains records of documents produced pursuant to LDR requirements.	7(a)(6)								
			Τ	Treatment Facilities, including PBP and RRR Facilities									
/				Dilution not used as a substitute for treatment.	3								
				Facility tests wastes or treatment residues to determine compliance with applicable treatment standards in accordance with waste analysis plan.	9 7(b)								
/				Certification and/or notification sent with shipments of waste.	7(b)(4), (b)(5), (b)(6)								
				Land Disposal Facilities									
		1		Facility tests wastes received to assure compliance with applicable treatment standards	. 7(c)(2)								
	Ţχ		Τ	Facility land disposes of restricted waste only if it meets applicable treatment standard.	40								
	1/\			Facility retains copies of generator notifications and certifications.	7(c)(1)								

## COMMONWEALTH OF SEWAS /LVANIA - DEPARTMENT OF ENVIRONMENTAL RESOURCES BUREAU OF WASTE MANAGEMENT

## INSPECTION REPORT COMMENTS

Date of Inspection	11-2:94		Identification Number	PADOO5028647
Company/Facility/Site Nam	• The	Electric	Materials Co.	
Brian Mummert (DER large volumes of va operations on site. discharged to the N site in a distillat acid pickling waste waste water pretrea waters. Under the d regulations the ope	Residual Wrious RCRACYanide Worth East ion unit. water und tment systefinition ration of	Waste Cook Wastes Waste	rdinator). TEMPCO and conducts two pers are treated or POTW and stoddard st year TEMCO had The facility now continually adjustand section 265.1 losed system is not and section 265.1	n site before being solvent is reclaimed batch neutralized an operates an automated ts the pH of the wast
waste streams. Plea regulations (amende type of RCRA waste closely and the req	se be advi d 1-16-93) generated uired writ	sed that required on site. ten SRS	section 262.80 o s generators to d Section 262.80 s should be develop	n file for the RCRA f the hazardous waste evelop a SRS for each hould be reviewed ed by 12-30-94. A copepartment after the e
storage tanks locat officials indicated which is manifested five was labeled "w store RCRA waste in 265.194(d) to label minimum, tank numbe	ed within that tank off site aste water tanks are tanks are five sho	the plant number as a character required to accurate to accurate to the material could be material to the plant of the pla	t. During the institute contained was racteristic hazard. Please be advised under section 2 rately identify thatked "waste stode	ste stoddard solvent dous waste. Tank numb sed that generators to 62.34(a)(2) and
•			3	
formal notification of any viole either violations noted herein, of This report does not co- deemed to grant or imply immu-	ations observed di or other violations i nstitute an order inity from legal act in interviewed do	uring the inspection of the inspection of the inspection of the inspection for any violation for any violation for any violation for inspection of the inspe	tion. Additional notification of sult of review of laboratory analy lable action of the Department tion noted herein. rily imply concurrence with the	tive of the Department. This report is fividiations may be issued concerning year or Department records.  1. Nothing contained herein shall be the findings on this report, but does
Person interviewed (sign	ature)		0.	11- 4-94

on

Page 5 of 6

# COMMONWEALTH OF SIMMS (LVANIA DEPARTMENT OF ENVIRONMENTAL RESOURCES BUREAU OF WASTE MANAGEMENT

## INSPECTION REPORT COMMENTS

Date of Inspection 1-2-94	L	Identification Numb	Der PADWSSZEGYZ
Company/Facility/Site Name	The Electric 1		
PBR units are routinely 262.40(e), 264.73(5) and inspection. Please revie	inspected, do 265.195(d) o w the approp	ocumentation as could not be lo riate sections	cated during the
	rs were labe	led, dated and	site at the time of the sealed. The accumulation
6. Documentation of the 262.34(a)(5) and 265.16 and develop/document an regulations by December	was not on fi employee tra	ile. Please rev	riew section 265.16 closel
waste, the quarterly rep Please mark all waste co Manifest PAE1105915 date quarterly report listed	ort indicated des in the appled 7-28-94 lis 2400 pounds	d that the wast opropriate boxe sted 1600 pound of waste. Pleas	
waters to the POTW and i	The department of the 10-24-1 corportate in the discharge in the corportate in the corporate in the corportate in the corporate in the	ent suggests th 94 discharge of preventative me s are prevented	at TEMCO review the untreated cyanide waste
			•
formal notification of any violations observed the either violations noted herein, or other violations noted herein, or other violations not constitute and deemed to grant or imply immunity from less than the constitute and deemed to grant or imply immunity from less than the constitute and deemed to grant or imply immunity from less than the constitute and deemed to grant or imply immunity from less than the constitute and deemed to grant or imply immunity from less than the constitute and deemed to grant or imply immunity from less than the constitute and deemed to grant or imply immunity from less than the constitute and deemed to grant or imply immunity from less than the constitute and deemed to grant or imply immunity from less than the constitute and deemed to grant or imply immunity from less than the constitute and deemed to grant or imply immunity from less than the constitute and deemed to grant or imply immunity from less than the constitute and deemed to grant or imply immunity from less than the constitute and deemed to grant or imply immunity from less than the constitute and deemed to grant or imply immunity from less than the constitute and deemed to grant or imply immunity from the constitute and deemed to grant or imply immunity from the constitute and deemed to grant or imply immunity from the constitute and deemed to grant or imply immunity from the constitute and deemed to grant or imply immunity from the constitute and deemed to grant or imply immunity from the constitute and deemed to grant or imply immunity from the constitute and deemed to grant or imply immunity from the constitute and deemed to grant or imply immunity from the constitute and deemed to grant or imply immunity from the constitute and deemed to grant or imply immunity from the constitute and deemed to grant or imply immunity from the constitute and deemed to grant or imply immunity from the constitute and deemed to grant or imply immunity from the constitute and deemed to grant or imply imply immunity immunity from the	ved during the inspecti tions identified as a rest order or other appeala gal action for any violati ed does not necessari	on. Additional notification ift of review of laboratory a ble action of the Departm on noted herein. ly imply concurrence with	ntative of the Department. This report is an of violations may be issued concerning nalyses or Department records. Sent. Nothing contained herein shall be the findings on this report, but does
Person interviewed (signature)			Oate
Inspector (signature)		RGin	Date

Page 6 of 6

Change Name, Contact, Add owners Address, Add Waste Codes.

# RESOURCE CONSERVATION AND RECOVERY INFORMATION SYSTEM MAINTENANCE FORM FOR EPA NOTIFICATION

EPA-ID# 1/1/1/1/01/01/51/01/21/81/21 Date: 3-7-94
FACILITY NAME Electric Materials
New Facility Name
Name Change The Electric Materials Co.
Location of Installation
Street
City/TownStateZip
County Code County Name
Installation Mailing Address
8treet
City/Town State Zip
Installation Contact
Last Name Wilcox Pirst John
Job Title Manager Phone #
Street
City/Town State Zip
Ownership
Name of Legal Owner the Sectric Materials Co.
street P.O. Box 390
city/Town North East State PA Zip 16428
Phone # (814) 725 - 9621 Land Type P Owner Type P
Waste Codes
Dolete Old Waste Codes Add Hew Waste Codes
DOOD DOOD FOOD DOOD FOOD DOOD THEE DOUD
F003 F005 D035
updated in ECRIS by RR Date 3. 1794
Updated in RCRIS by R/C Date 3- 1/79

	Type	RCRA Reg.	RCRA Reg.	
Waste		Status	Desc.	
Activity	•		2020.	
	•		•	
Generator		•		
TSD .		·		
Transporter Mode of Trans	portation:	· _ ·		
Air	Rail Hi	ghway Water	Other	
Burner/Blende	r			
Bullering	B Boiler an	d/or Industrial Furna	ce (BIF) only.	
	D BIF only:	Smelter Deferral.		•
		Small Quantity Exemp	tion claimed	
		ner/Blender, Verified		
		ner/Blender Activity.		•
	Blank Unverif	180.	ye.	
HWF Market to			· /	
		cates that the handle		
		I in marketing to burn	ners of hazardous	Waste
•	fuel ac	ctivities.	•	
	Blank No act:	ivity.		
HWF Other Ma	rket	<u>.                                      </u>		•
		icates that the Handle	er is engaged in	
		ous waste fuel marketi		
		tor marketing to burn		
HWF Burner	9-11-1	to a manufact to begin		: •
THE PULL -	B Boiler a	nd/or Industrial Furn	200	
		on of activity.		ź
oso Market t		on or accivity.	•	•
USU MATREC L				_
		licates that the handl		
		in marketing to burne	irs or orr-spec.	1260 011
	fuel.	;	•	
oso other Ma				
•		dicates that the Handl		
		ng of off-spec. used o		
		or marketing to burnes	r (e.g., marketin	g to
	used oi	l refinery).	•	
OSO Burner_				•
		and/or Industrial Furn	nace.	•
•	X Indicat	ion of Activity.		
SO ACT:				
	Code in	dicating that the han	dler is engaged i	n
	marketi	ng of specification f	uel oil activitie	<b>3</b> •
	B Boiler	and/or Industrial Fur	nace.	•
		ion of Activity.		
Burner Type				-
			Ind. Furnace	<b>-</b> .
Underground	Injection Con			
		ndicates that the Hand		
	treats	, stores, or disposes	of hazardous wast	
	and ha	s an injection well lo	cated at the inst	callation
Recycler:_				
_	C Commer	cial ·	•	
	R Non-Co	mmercial Recycler		·
•		Recycler, Verified		
		recycler, unverified		

Please refer to the instructions for Filing Notification before completing this form. The

Ay		Tic	Received alVaEOU CTION
₹.	1 13	υĽ	CHOM
i.	3 0	4	1004

re Oi	quir the	ed by	urce urce	Secti Cons	i heri ion 30 ionvat	010		Y		Un	ited	State	s Er	viro	nmer - A	A	Ct	lvi ction	ty.	Acy	.5	EC į	10.	EB	) 0	4 1	994	٧	
ı.	ine	talie	lon'	EP.	A ID	Nur	nber	(Ma	rk 'X				oprk	ste i	ox)														
		A. I	iret	Noti	Noati	on	Х				juen te <i>It</i> e			itlor	1		F	<b>4</b> <i>P</i>	PE	c. BG/	_		C	100	2	378	<b>V</b> .	11/2	
II.	Na	me c	of In	etalls	itlen	(Inc	lude	cor	npei	ny a	nd <b>a</b> j	ecifi	ic si	te n	eme,														
Т	h	le	Τ	E	1	e	С	t	r	i	c		М	а	t	е	r	i	а	1	S		С	0					
11	. Le		on o	ins	talla		(Phy	sice	l ad	dres	a no	P.O	. Bo	X O	Rou	rte N	umt	er)	>										
S	ree	ŧ																	<b>,</b>					, ::::::::::::::::::::::::::::::::::::					1/87
5	0		S	0	u	t	h		W	a	s	h	i	n	g	t	0	n		S	t	r	e	e	t	1			
- 5	ree	t (co	ntin	ued)	T	Τ	T	T	T	T	T T		<u> </u>	Ι	T	l I	Ī	l T	Π	T					Γ	Γ	Ī		T
*****		<u> </u>	1			<u> </u>	<u> </u>	<u> </u>	<u> </u>	<u> </u>	<u> </u>					<u> </u>			200.00	3 - 1.1		.3833			<u> </u>	<u> </u>		Ц_	1
	ty c	er To	Τ.	Τ.	Т	Ι.	Т	т	Τ	<del>,                                    </del>	T T	I		ī	T	<b>,</b>		Sta	1 <b>0</b>	1	Coc				ī	ı —	T T		T T
N	0	r	t	h	<u> </u>	E	a	s	t	L	<u> </u>			<u> </u>	1	<u> </u>		P	Α	1	6	4	2	8	-	<u> </u>			<u> </u>
Cot	inty	Cod	C	ount	y Na	ime	<del>,</del>	,	,	т —	τ	1			т	T -		1	1	1	¥ .			1		<del></del>	,	1	
			Ε	r	i	e			<u> </u>	<u></u>																			
ΓV	. In	stell	ntion	Wal	ling .	Add	reas	(Se	e Ins	truc	tion		,																
S	r <b>ee</b>	tor	P.O.	Box																									
P	0		В	0	x		3	9	0																				
C	ty o	r To	WN															Sta	te	ZIP	Coc	ie							
N	0	r	t	h		Ε	a	s	t									Р	Α	1	6	4	2	8	-				
٧.	Ine	talla	tion	Con	tact	Per	son :	to b	e co	ntec	ted i	ega:	rdin	y w/	ste	ectiv	ttes	at s	ite)	•									
N.	113	(lee	e)												(Air	11)													
W	i	1	C	ō	х										J	0	h	n											Ī
J.	ЬΤ	Hie	1			<b>.</b>					1				PI	one		nbe	e fan	e co	de ar	าต์ สน	umbe	n .	<b></b>	١			
М	·	n	а	g	е	r		Γ	Γ		<u> </u>				8	1	/1	_	7	2	5	_	9	6	2	1	1		
	******	*********			*********	L Artr	rest	/S-	e in	27711	tlor.		<b>&gt;</b>		U	Ι	4		_ /	4	71		9	L U		1 1,			
<b>1.</b> (	on	act.	Addi	688	2011/12/12/12		et or					IA					100000			Signal.		333333							
L	atio X	•	Maii X	10							Ī			3388.0			10:15:10		use gare	П		1.000	990	673833					
		Tov	1							l								Stat		ZIP						<u> </u>			L
CII	y UI		T												Γ			318	<b>O</b>	215		18	800 T	2000					
<b>V</b> 1		L.	n lalar	184		****	tion	77b.																					
							egal		)er									¥81.											
T	H	L	,	E	1	_		±S	~	i				м					<u>.</u>		,			<u></u>		Caral Departure	(A) (100 M		
	-		D. B	لبالبا	r Ro	ute	Num		ليقع	Ц_	لنك				للظا	ليات	е .	r 🗆		La_	<b></b> _	S.I		لنك	۵				
					T	5 1 <b>7</b>							$\neg$	Ø 5.			П				Ī	П	1			9,000,0			
P	0 tv 0	r To	B	0	Х		3	9	0				1		لبا	_	-	64-		r							1		L
7		1	r		T												-	Sta		ZIP			_ ]	1	1277	2300	· 🐬		
N	0	r	<u>t</u>	h		Ε	a	s	t			ᆗ		T				P	A	1		4	2	8	- I				
P	one	Nu	mbe	r (are	<b>98 CO</b>	de e	nd n	umbe	er)	S. V		B. L	and	i ype	10.	Own	eri) ~~	/P®	D. C	hang	e of i	r 	₽F F	Mor	nth .	Di	nged Y	Yeq	4
ρĺ	1	1,	-	7	2	5	-	a	6	2	1	1	D			Г		- 1	Yes		No	$_{\mathbf{v}}$							

		ID - For Official Use Only
VIII. Type of Regulated Waste Ac	Livity (Mark X' in the appropriate boxes.	Refer to Instructions.
	rdous Waste Activity	B. Used Oil Fuel Activities
Generator (See Instructions)     a. Greater than 1000kg/mo (2,2 b. 100 to 1000 kg/mo (220 - 2,2 c. Less than 100 kg/mo (220 lb)     Transporter (indicate Mode in both a. For own waste only b. For commercial purposes  Mode of Transportation 1. Air 2. Rail 3. Highway 4. Water 5. Other - specify	(00 lbs.)  4. Hazardous Waste Fuel  a. Generator Marketing to	1. Off-specification Used Oil Fuel at Generator Marketing to Burne b. Other Marketing to Burne b. Other Marketing to Burne c. Burner - Indicate device(e) - Type of Combustion Device 1. Utility Boller 2. Industrial Boller 3. Industrial Furnace usation 2. Specification Used Oil Fuel Market (or On-site Burner) Who First Claims the Oil Meets the Specification
A. Characteristics of Nonlisted Hazar wastes your installation handles. (See 1. Ignifiable 2. Corrosive 3. Reactive (D001) (D002) (D003)	ee 40 CFR Parts 261.20 - 261.24) 4. Toxicity Cheracteristic	nding to the characteristics of nonlisted hazardous  number(s) for the Todotty characteristic contaminant(s))  to list more than 12 waste codes.)
7 8	8     F     0     0     7     D     0     1       9     10       0     F     0     0     3     F     0     0	5 D O 3 5 D O O 1
<b>1 2</b> F O O 1	s requiring a handler to have an I.D. number. S	See instructions.)  5  6
accordance with a system design submitted. Based on my inquiry of gathering the information, the inf	led to assure that qualified personnel in the person or persons who manage the sylormation submitted is, to the best of managers of the self-inguities is a significant penalties for submitting false is a significant penalties false is a significant pen	prepared under my direction or supervision in properly gather and evaluate the information ystem, or those persons directly responsible for my knowledge and belief, true, accurate, and information, including the possibility of fine and
James E. Johnson	James L. Johnson, V.P.	- Gen. Mgr. 1/24/94
XI. Comments	4	
Note: Mail completed form to the appr	opriate EPA Regional or State Office. (See Sc	Section iii of the booklet for addresses.)

THE ELECTRIC MATERIALS CO.

MANUFACTURE

Toll Free Number Telex 387783

(814) 725-3620

EPA REGION

February 9, 1994

U.S. E.P.A. Region III RCRA Programs Branch Pennsylvania Section (3HW51) 841 Chestnut Building Philadelphia PA 19107

BOX 390

(814) 725-9621

NORTH EAST, PA 16428

Subject: EPA Form 8700-12 and 1993 Hazardous Waste Report

To Whom It May Concern:

Enclosed is the EPA Form 8700-12, corrected, and the 1993 Hazardous Waste Report.

As per our phone conversation, Section II, the correct name of the installation is The Electric Materials Company. Section VIIA, name of installation's legal owner is The Electric Materials Company. Section IX, description of regulated waste, contains the list of current wastes.

If there are any questions regarding either of these reports, please contact me at 814-725-9621, extension 297.

Sincerely,

THE ELECTRIC MATERIALS COMPANY

John Wilcox

Safety and Environmental Manager

JW/pc

Mess	DIII	n or t	VDE W	ath £ L	111. 1	voc (1.	2 chai	ncler:	ne i	/14.Fe	or the	onsh	adeil	bira.	(m.t.					Liver	Apr		1852	<b>V</b> .5		kan ing			y to the
1								Uni	ed S	ales	Envi Vashi	ronn	nenta n, DC	Pro 204	tection 60	on Ag			cti	vit.	,	Film this her	lorn I is	eler otifica The requ	to th	e Ins belor rmati by	11 UE (	tiore mpie sques	HI.
	-				-	, (11	100		,,,	<u> </u>	110		Tu	Ju	5 V	70	-		Cti	VIL	<b>/</b>			the f overy			, ons	6.15	
For	Off	ICIB	I Us	e O	niy									Com	men	ls											· ·		
C_																	!		Ī		:								
c							!								ļ	!	· 	<u> </u>					SE						
				In	stail	ation	's EP	A ID	Numl	nec					_ A	фрго	ved		D (yr.	ate A	eceiv		BY)	 	드 [	V je Tisn	i E. dri <b>ad</b> ayi		
C													T/A	С		<u> </u>								1					
F I			1	talla	<u> </u>									1			<u> </u>		!				_\$	P 1	1	D.C.			LŒ
1. 14	2511)	e 01	ins																										-112
	Н		:	E	L	-			R	Ι	С		M	Α	T	Е	R	I	Α	L	S		C. î	0	M	P	Α	N	Y
11. fr	ste	illat	ion	Mai	ling	Ad	dres	S					S	00' 0		. Box													
C.				!		T-	<u> </u>	;					3"		1.0		!		T							-		-	
3	Р.	0.	<u> </u>	В	0	X		3	9	0	Ĺ	<u>L</u> _	<u> </u>		<u> </u>	<u> </u>							_	;				<u> </u>	
C.			ī	i -	Ι	Т	1			Cit	10 Y	own	Γ-	T	Γ	Τ	<u> </u>	1	T-			I	S	tate	_	Z	IP Co	ode	
4	N	0	R	T	Н		Е	Α	S	T													P	Α	1	6	4	! 2	8
111. (	.00	atio	n o	ins	tall	atio	n													,								•	
C		<u> </u>	T	I	Γ	1	T		·		Γ	<u>s</u>	treet	P 10	oute	Num	pei	1	T					1		i		T	
5	5	0		S	0	U	Т	Н		W	Α	S	H	I	N	G	Т	0	N		S	Т	R	E	E	T	<u> </u>	!	:
		,		1		1				Cit	y or	Town	<b></b>			T	1					τ	s	tate	_	. 2	IP C	ode	
6	N	0	R	Т	Н		Е	A	s	Т						j							Р	Α	1	6	4	2	8
IV.	ns	talla	tion	Co	nta	ct																							
-			т		т	Nat	me a	nd Tit	le (/a	st, fii	SI, BI	nd jo	b title		AFE	কত		т -	<del></del>	<del> </del>	Pho	ne N	umbe	er (are	ea co	de a	חל חנ	ımbe	17
2	W	1	L	C	0	X		J	0	Н	N			1		TOR				8	1	4	7	2	5	9	6	2	1
V. (	)w	nen	hip																								, i		
			Т	<u> </u>	· T	1	<b>A</b> .	Name	of Ir	ıstall	ation	's Le	gal C	)wne	<u> </u>	Т	T	Т	Т	Γ-		В	Тур	e of (	Own	ershi	р <i>(еп</i>	ter c	ode.
R	N	Α																				PR	IVA	TE	COR	POR	ATI	ON	
VI.	Ty	эе о	f Re								ark	'X' ii	n the	e <b>a</b> p	prop	riat	e bo	xes	Ref										1
<u> </u>					l. Ha	zard									+-	7 -				B. U				<u>ctiviti</u> IA	8				
			erato				L	J 1b.	Less	thar	1,00	00 kg	/mo		-	1 6. ( 1	Dff-S ente	pecif	icatio and n	n Us nark a	ed Oi	il Fue pri <b>a</b> ti			low)	1			
			•		/Dis	poser												a. Ge	enera	tor M	arket	ting t	o Bui	rner					
			-	and le	-													b. Ot	her A	1arke	ter								
ľ						ardo:				low)	ı					_			ırner										
		_		nera her N		Aarke	ting 1	o Bu	rner							J 7.	Speci Who	ificat First	ion U Clain	sed C	il Fu Oil	el Ma Meet	orket s the	er <i>(or</i> : Spe	On .	site B ation	urne	nA	1
			c. Bu		VIBIK	eter																							
VII	W	aste	Fu	el B	urni	ng:	Тур	of	Con	ıbu:	stio	n De	vic	e (en	ter 'X	' in a	ll app	ropr	iate b	oxesi	o ina	licate	type	of co	mbu	stion	devi	ce(s)	in
	in n NA	<b>8</b> 2870	dous	_		e <i>l or o</i> Jtility			ation	used	9 011 1			nea. Iustri			ction	is tor	defir		•			<i>n aev</i> Furni		,			
		lod	e of		_		-		nspo	rte	rs oi						е вр	pro	priat										
	Α.		_	B. R				ghwa		_	). Wa					(spec		NA											
						nt N																							
Mar noti	k 'X licat	in lion.	the a	ppro s is n	priat	e box our fir	to ir	dica:	e whion,	ethe	r this	s is y	our i	nstal on's	latio EPA	n's fi ID Nu	rst n	otific r in t	ation he sp	of ha	rovid	lous v	waste	e acti	vity	or a	subs	eque	nt
_																					C. In	stalla	tion	s EP	A ID	Numl	oer_		
	A.	First	Noti	ficati	on	IX.	B. Su	bseq	uent	Notif	icatio	on <i>(cc</i>	mple	te ite	m C	,		P	A	D	0	0	5	0	2	8	6	4	2

														L				10 -	For C	fficiel	Use (	Only			1
														_	<u> </u>									1	A C
X.	Des	crip	tior	101	Haz	ard	ous	Was	tes	(co	ntin	ued l	rom	ront)											***
A.	A. Hazardous Wastes from Nonspecific Sources. Enter the four-digit number from 40 CFR Part 261 31 for each listed hazardous waste from nonspecific sources your installation handles. Use additional sheets if necessary																								
			1				, 2	2				3			T	4				5				6	
					1				_	1			7		1	i	T	1 1			i	1	,		
	F	0	0	1	]	F	0	0	6	l			i			-			1						
			7				E	В		]		9				10		1 1	-	11		1		12	
			-																					:	
R	Hazai	rdous	Was		L.	Sne	cific 1	Sour		Ente	L	four	digit n	umber	from	40 CFR	Part 2	61 33	101.0	ach lies					
	speci	ific so	ource	s you	ur ins	stalla	tion h	andl	es. l	Jse a	dditio	onal si	heets i	fnece	SS#TY.	. NA		01.52	. 101 61	1011 1151		28,000	15 ** 85	te moin	ļ
	Т		13				1	4		T		1!	5	$\neg$	Τ_	16				17				18	
		i		:	1					1			T	_		i	·	1 1	Ī	T	- <del></del>	1  -			1
					1					1				-	1 1				ì			1 1	,	: :	1 1
		-	19		1		2	.c		1		2	1			22		1 1		23		1		24	
				!	1					1		Ī	Ī				Ī	1		Ī		1	i	. ;	
			<u> </u>	i	1	<u> </u>								_				1 1				lL			
	<u> </u>	,	25	,		<u> </u>	. 2	€			<u> </u>	2	7	_	<u> </u>	28		1 1		29				<b>3</b> 0	
					:									-		1							i	•	
-	Com		ial C	ham		2-04	L		1000	W-		Enter			<u> </u>	ber fron	40.0	EP Pa	n 261	22 (00			1	<u> </u>	
																ets if n				.33 101	eacn	cnemi	cai su	DStance	,
			31		T		3	32		T		3:	3		Ι	34		П		35				36	
		i		<u> </u>	1		ΠĬ			1		ΓŤ		-1	1	T	1	1 1		T	1	1		T	
			ŀ				1											1 1							
			37		1		3	38		1		3:	9			40		1 1		41		1 [		42	
		-																							
	-	<u> </u>	<u></u>	<u> </u>	┨				<u> </u>	┨	-			$\dashv$		46		1 1		47		┨			
		T	43	T	1		<del>- 1</del>	14		1		4	<del>-</del>		$\vdash$	40	<del></del>	1 1	T	<del></del>	Т	1 1		48	
	1				1										}							1 1			
D.	Liste	d Inf	ectio	us V	/aste	s. Er	nter th	ne for	ur-di	git n	umbe	r from	40 C	R Par	1 261.	34 for e	ach ha	zerde	ous wa	ste fro	m hos	spitals	veter	inary h	05-
	pitals	s, or r	nedio	cal a	nd re	sear	ch lab	orato	ories	γουι	insta	allatio	n hand	lles. U	se add	litional	sheets	if ne	cessar	y. NA	1				
			49				5	50				5	1			52				53				. 54	
																						$\  \cdot \ $			
F	Char	ecter	istic	L of I	l Nonl	ietad	Haza	rdo	L W	acte:	. Ma	rk 'X'	in the	hoxes	COLLE	pondin	n to the	A cha	racteri	stics o	f nonl	isted b	azard	OUS WA	stes
							e 40 (								000	<b>,</b>						,0100 ,		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
		Г	J 1.	lanit	shie					(X)	2 0	orrosiv	<b>/</b>			П	3. Rea	active	<b>h</b>			E	🗓 4. 1	oxic	
				(000								C02;					(DO							000)	
ΧI	XI. Certification																								
	I certify under penalty of law that I have personally examined and am familiar with the information submitted in																								
	this	s an	d all	att	ach	ed d	locun	nen	ts, i	and	that	base	ed on	my i	nquii	y of th	nose i	indiv	ridu <b>a</b> l	's imn	nedit	stely i	respo	nsible	e for
	obt	aini	ng ti	he ii	nfor.	mat	ion, l	bel	eve	the	et the	sub	mitte	d info	rma	tion is	true, i	accu	rate,	and c	omp	lete. i	am a	ware	that
L			re si	gni	ICA	nt pe	enent.	iesi	or s	uDI	nitti					, inclu			OSSIL	πιτη σ					ent.
Si	gnetu	ire			1							Ne	me en	d Offi	ciel Ti	tie (type	or prii	nt)			1	Dete S	igned		
	John Wilcox, Safety Director 7/22/91																								

EPA Form 8700-12 (Rev. 1/1-85) Reverse

## Panarylvonic Department of Environmental Resources Bureau of Weste Monagement

Gen

## Hazardons Waste Inspection Report Generators — Part A

Date of inspection $9-13-90$ Time start $09:30$ Time finish $15:15$
Name of inspector Richard E. Strawn
Company, installation name The Electric Materials Co.
Location 50 South Washington St., North East PA 16428
County Erie Municipality North East
Identification number PAD 005028642
Name of responsible official John Wilcox
Tille Safety Director
Mailing address 50 South Washing ton Ste, North Fost, PA 16428
Area code and telephone number 814-725-9621
Name of person interviewed John Wilcox and Pat Gallagher
Tille Safety Director and Mar- Plant Engineer
Mailing address (If different from above)above
Area code and telephone number
1. Current waste handling method:
a. 🕱 On-site 🗆 treatment, 🗆 storage, 🗀 disposal 🔭 PBR
b. 🕱 On-site 🗆 use, 🗀 reuse, 🗀 recycle, 🎉 reclaim
c. 🔀 Off-site 🔀 treatment, 🗆 storage, 🔀 disposal
d. 🗷 Off-site 🗆 use, 🗀 reuse, 🗀 recycle, 🔀 reclaim
2. Amount of hazardous waste produced:  (Based on Manifested)
a. 744,658 kg./mo. Shipments and the Annual b. 7535,900 kg./yr. Report (PBR) for 1989.
b kg./yr. / neport (FBR) 101 . 107.  See Comments
3. Types of hezardous waste produced by Hazardous Waste Number and destination facility (include location and type).
Waste Number Destination Facility Location and Type  FOOI Safety-Kleen, Hebron, OH Reclaim (TCE)
FOOL Unknown - Suspected Shipped as Doo2
FOO7 Treated under PBR
DOOL Sofety Kleen, Hebron OH Reclaim (Stoddard Solvent)
DOOL Safety- Kleen, New Castle, KY Reclaim (Stoddard Solvent)
Dool Safety-Kleen, Linden, N.J. Incinerate (400 71000 ppm)
DOOD, DOOB Frontier Chemical, Niagara Falls Treatment (wwtP)
Doo2 Frontier Chemical - possibly on FOOG
2 4 No. 10 10 10 10 10 10 10 10 10 10 10 10 10

#### Pannsylvania Department of Environmental Resources Bureau of Wasta Management

# The Fleetric Materials Co.

# Hazardous Waste Inspection Report PAD 005 028 642 Generators — Part B 9-13-90

		1-46	Viela	ition Observed 2—Not Applicable 3—Not Determined 4—Non Comp	Chapter		
Status				REQUIREMENT			
L	2	3	4		75.262		
				Hazardous waste determination, copies available See Comment #2	(b)		
1				Identification number	(c)(1)		
$\overline{I}$			$\neg$	Hazardous waste shipments offered only to licensed transporters	(c)(4)		
				Authorization received from TSD facility for wastes shipped off-site	(d)		
1				PA manifest used for intrastate shipments	(e)(2)		
/				Disposer state manifest or EPA amor manifest used for out-of-state shipments	(e)(3)		
十				Manifests filled out properly and completely	(e)(7)		
1		/		Manifests routed properly and within time limits (7 days)	(e)(14) or (15		
1	1			Proper U.S. DOT shipping containers or packages	(f)(1)(i)		
1	$\neg$			Shipping containers marked and labeled according to U.S. DOT	(f)(1)(ii)		
1	$\neg$			Containers of 110 gal. or less marked with required PA label	(f)(1)(iii)		
T	$\neg \uparrow$	1/		Placards offered to transporter	(f)(2)		
才		-	•	Wastes accumulated on-site for less than 90 days	(g)(1)(i)		
1			X	Wastes stored in proper containers and properly marked and labeled	(g)(1)(ii)		
$\top$			X	Containers managed in accordance with 75.265(q)(1)- 4 14) See Comment 4	(g)(1)(iii)		
1	•			Containers clearly marked with accumulation date and visible for inspection	(g)(1)(iv)		
1				Records retained at designated location for 20 years	(h)		
7			-	Quarterly reports submitted to the Department	(i)		
7				Exception reporting procedures followed	(j)		
1				Hazardous waste disposal plan, if required	(1)		
		~		Spill reporting procedures followed	(m)(1)		
1				Preparedness, Prevention and Contingency Plan and implemented	(m)(5)		
		V		Special requirements followed for international shipments See Comment 2  On the job or classroom personnel training program [75.265(f)] See Comment 5	(0)		
			X	On the job or classroom personnel training program [75.265(f)] see Comment 5	(g)(1)(6)		
1				Drum accumulation area inspected weekly as per 75.265(q)(5)	(g)(1)(iii)		
7		/	$\mathbb{X}$	Special requirements for reclaiming has waste see Comment # 7	261.6 C		
$\dashv$			-	See Comment 7			
_					-		

#### Pennsylvania Department of Environmental Resources Surses of Waste Management

Date of Inspection	9-13-90	Identification Number	PAD 0	05 028 642
	amo The Electric	Materials Co		
		Municipality		
			•	
1. The Elec	trie Materiala	Co. (TEMCO)	should	maintain
proper s	econds of the	volumes of	stadds	al solvent
	d on-site in			
_should	be shown	on the Qua	rterly	Reports.
	umes shows		, v. //	•
	include wh			
`				
2. Two sep	mate wasto.	atreams are.	being t	rested under
PBR	(a) In one app	eration an a	cid wo	este from
a pickl	ing / quenchi	ng operation	u is	neutralized
with No	OH in a 1,50	ogallar tan	k as	a batch
	n. The sleet			
	through a fil			
sent to	Moranda (??)	in Montres	I, Can	ada to
	metals (cap			
should	supply this	affice with	a Con	nplete
_analysis		of the	filter	cake
and do	cumentation (	receipta) si	rowing	where it
has be	een sent rece	ently, (b)	<u>In</u>	a second
- operation	n cyanide	bearing w	aste i	voters from
at least	four seps	rate electro	platin	a operations
are bot	the treated in	a 1,000 g	allon'	tank:
Resources, Bu inspection are are indicated. analyses and I	n report is official notification ureau of Waste Managemen a shown in this report. Any Violations may also be dis review of Department record d herein and listing any add	nt, inspected the above in violations which were us scovered upon examinated is. Notification will be for	installation. T incovered du ion of the re	The findings of this ring the inspection sults of laboratory
Person Interviewed (signs	ature) Mailes	Certified	Date	9-20-90
Inspector (signature)	Richard E. S	traun	Date	9-14-90
				Duge # 3 of 5

## Pennsylvania Department of Environmental Resources Bureau of Wests Management

	or <u>FAD 003 028642</u>
Company, Installation Name The Electric Materials	Co (TEMICO)
County Municipality	North East
During the inspection, it was es	plained that the
sludge (FOOG) from this open	,
off and placed into 55 gallor	
a review of the Questerly Repor	
for the past two years has n	at shown ann
FOOL ever having been as	lipped from this
facility a a statement on the	Oursterly Reports
indicate that this sludge ho	
a metal reclaimer. By Oct 12	1990 TEMCO should
supply this affice with full of	Louisentation
(including an analysis)	to verily
that this sludge has comm	ercial re-sale
value and where it has be	
3. Prior to treatment, the cyanis	
waters are stored in a 2,500	
tanke a remote reading tan	
this tank did not appear to	be accurate. This
gage should be repaired or	replaced immediately
4. a shipment of hazardous	waster was made
on Sept 6, 1990. Only one dry	m of FOOL (TCE)
was ready for disposal and	ne drum of DOOL
(staddard solvent) was partially	full by the stille
This inspection report is official notification that a representative of Resources, Bureau of Waste Management, inspected the above inspection are shown in this report. Any violations which were are indicated. Violations may also be discovered upon examinantlyses and review of Department records. Notification will be tions indicated herein and listing any additional violations.	e installation. The findings of this a uncovered during the inspection nation of the results of laboratory
Person Interviewed (signature) Mailed Catified	Date 9-20-90
Inspector (signature) Richard E. Strauen	Date 9-14-90
	page "4 of 6

## Pennsylvania Department of Environmental Resources. Surean of Wasta Management

Date of Inspection	9-13-90	ldentificatio	n Number $\mathbb{Z}_2$	7D 00	5028642
Company, Installation Na	me The Electric	Materials	Co (	TEM	(0)
	iè		No.		
This dru	m was bee	na used t	l accu	muls	te waste
hom the	e stell and	would h	e user	d to	transport
	eto from the				
	stadard				
	hould be.				
	taining w	, , ,			<i>u</i> ,
	plete trainer				
	ed by Oct				
	should				
6. This for	wilty used i	to generate	two o	wheel	alustan
	One is no				
	w Landfill				
for Pb	and Cd.	according :	to Mr.	Wil	COV, TEMCO
_ Changes	I alloys two	- years a	go in	d h	ave nat
	I amy ha				
_sincle.	Every drus	is now	tested	and	of the Cu
_ content	is greater to	Son 1070	the a	just, c	a mised
with or	e and sent	to noran	Ma (??	) from	<u> </u>
recovery	2. By Oct				
_supply	this office	with do	ument	ation	to verify
the also	ne.				
7. Of the	FOOL is being	ig legitim	stely s	eclass	ned (for
Resources, Buinspection are are indicated. analyses and re	report is official notifica reau of Waste Manager shown in this report. A Violations may also be eview of Department red I herein and listing any	nent, inspected the ny violations which discovered upon e ords. Notification w	above install were uncov xamination o vill be forthcol	lation. The ered during f the resu	e findings of this ng the inspection ults of laboratory
Person Interviewed (signa	ture) <u>Mais</u>	led Certifico	1	Date	9-20-90
Inspector (signature)	Richard &	Shawn		Date	9-14-90
				Da	00 #5 of 6

#### Pennsylvania Department of Environmental Resources Suress of Wests Management

Date of Inspection	9-13-90	ldentif	ication Number ${\Bbb Z}_2$	003	028642
Company, Installation N	ame The Electri	e Materia	15 Co. C7	TEINC	<u>:o)</u>
County	Erie	Municip	vality <u>Nort</u>	h Ea	5t
this wast 261.6 (6) in viole determine	TEMCO is te as a ho elt appea ation of elt ation of the waster or	gardous no at the Les makes FOOL als	waste is time the ing an in	ender at The sprap ships	EMCO is
mat soh	out the gr	ant tien	amente.	l at	alland
	5 with the				
8. It is A	ecommended	that	Leture ans	Insia	be done
using	the TCLP	Ctoxists	christere	itic.	leashing
muedu	e) while is	required	under Les	laul 1	law.
9. Please	be advise	I that y	Section F	el-10,	1990 the
Pa Hays	be advise Was	te Regul	ations we	ne so	- mumbered
	****				<i>(</i> '
	A .			· (	
			$\overline{}$		$\overline{}$
<del></del>	1	<del>}</del>	<del>)</del> -		<del>-\</del>
	<u> </u>				<del></del>
					<del>//-</del>
	(				
Resources, B inspection are are indicated analyses and	n report is official notification of Waste Manage shown in this report. Violations may also review of Department land herein and listing ar	gement, inspected Any violations w be discovered up records. Notification	I the above install which were uncover on examination of on will be forthcor	ation. The ered during f the resul	findings of this g the inspection Its of laboratory
Person Interviewed (sign	eature)	Miled Co	rtified	Date	9-20-90
Inspector (signature)	Kuhas	& C. Shar	vn_	Date	9-17-90 ge #6 of 6
				pa	ge 6 of 6

Inspector: Richard Strawn
Address: 1012 Water St
Manduille PH 16335
Telephone No: 8/4-332-6848

# RCRA LAND DISPOSAL RESTRICTION GENERATOR CHECKLIST

I. HANDLER IDENTIFICATION
The Electric Materials Co 50 South Washington St.  A. Handler Name  B. Street (or other identifier
A. Handler Name B. Street (or other identifier
North East PA 16428 Erie C. City D. State E. Zip Code F. County Name
Foundry, Forging, Machining Plating (19, Sn. Bl., No. and Cd) G. Nature of Business; Identification of Operations: SIC Code(s)
PAD 005 028 642
H. EPA ID #
Mr John Wilcox Safety Director 814-725-9621  I. Handler Contact (Name and Phone Númber)
1. Handler Contact (Name and Phone Number)
II. GENERATOR COMPLIANCE Comments
A. Waste Identification This facility
1. F-Solvents generates FOOI, FOOL
a. Does the handler generate the following wastes? FOO?, DOOI, DOON,
(1) F001, F002, F004, or F005 Yes No Dook, Dook wastes
(11) F003 —Yes —No No LDR
If an F003 wastestream (listed solely for ignitability) has been mixed with a non-restricted documentation was solid or hazardous waste, does the resultant mixture exhibit the ignitability characteristic? Awailable for any  Yes No Wastes.
b. Source of the above: Form 8700-12; Part A; Part B; Biennial/Annual Reports Facility generates other (specify)
Appendix A is intended to assist the inspector and enforcement official in determining whether the facility is generating F-solvent wastes, if such wastes were not identified by the facility previously. If you are concerned that

#### UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

#### **REGION III**

841 Chestnut Building Philadelphia, Pennsylvania 19107

SUBJECT: RCRA Inspection - THE ELECTRIC MATERIALS CO. DATE: SEPT. 23, 1987

FROM:

William L. Walsh, EPS

PA RCRA Enforcement Section (3HW11) WWW

TO:

File

Peter W. Schaul,

PA RCRA Enforcement Section (3HW11)

BASED UPON A REVIEW OF THE RCRA INSPECTION REPORT FOR THE FACILITY REFERENCED ABOVE, I HAVE DETERMINED THAT NO FURTHER ACTION IS REQUIRED AT THIS TIME.

#### MAZARDOUS WASTE INSPECTION REPORT Concrators - Fart A

•
Follow-Up
Date of inspection 8-19-87 Time start 10:00 Time finish 12:
Name of inspector Richard E. Strawn.
company, installation name The Electric Materials Co.
westion 50 South Washington St North East PA 16428
county Erie Municipality North East
Identification number PAD 005028642
Name of responsible official John Wilcox
ritle Safety Director
Mailing address 50 South Washington St. North East PA 16428
Area code and phone no. 8/4-725-962/
Name of person interviewed John Wikcox
Title Safety Director
Mailing address (if different from above) Above
Area code and phone no. Hhove
1. Current waste handling method: Follow - 4P
a. B On-site B treatment D storage, D disposal P-B-R
b On-site _ use, _ reuse, _ recycle, _ reclaim
c. Ø Off-site / troatment, / storage, Ø disposal
d. Ø Off-site Duse, Dreuse, Ø recycle, Dreclain
2. Amount of hazardous waste produced: Two 1000 gallon Butches treated sin
a. 6498 (Approximately) kg. to. Amount indicated on Last inspect.  h. Last inspection of 6-17-87 plus  Amount indicated on Last inspec.
bkg.Ar. Report.
3. Types of hazardous waste produced by Hazardous Waste Number:
FOO1, FOO6, FOO7 DOO2 DOO6 DOO8.
4. Are hazardous wastes transported off-site by the generator? [ Yes & No 7.3 ll. per gal. x 1000. gallons = 7333.llm - by 2.2 = 3333 Kg
7.3 ll. per gol. x 1000, gollons = 7333 llm - by 2.2 = 3333 ll

		<u> </u>		I- NON COMPLIANCE, Z-COMPLIANCE, 3-NOT APPLICABLE, 4-NOT DETERMINED							
	COMPHANCE STATUS 1 2 3 4			REQUIREMENT 7 1/ 1/D							
	1			Identification number	(c) (i						
	1			Hazardous waste shipments offered only to licensed transporters	(c) (4)						
	1			Authorization received from TSD facility for wastes shipped off-site	(a)						
		D		PA manifest used for intrastate shipments	(e) (2)						
	1			Disposer state manifest or EPA format manifest used for out-of-state shipments	(e) (3)						
	1			Manifests filled out properly and completely	(e) (7)						
1	V	1	1	Manifests routed properly and within time limits (24 hours)	(e)						
1	1	П		Proper U.S. DOT shipping containers or packages	(f)(1)						
				Shipping containers marked and labeled according to U.S. DOT	f) (1) (i						
X		H		See Comment 44 Containers of 100 gal. or less marked with required PA label	(f) (1) (i						
4	H		1	Placards offered to transporter	(f)(2)						
				Wastes accumulated on-site for less than 90 days	(g)(1)						
X		-		See Comment #4 Wastes stored in proper containers and properly marked and labeled	(g)(l)(						
	J	1		Containers managed in accordance with $\cdot 75.265(q)(1-9)$	(g) (1) (i						
V	1			Containers clearly marked with accumulation date and visible for	(g) (1) (:						
	J		1	Records retained at designated location for 20 years.	(h)						
-		r	H	Quarterly reports submitted to the Department	(i)						
	H		H	Exception reporting procedures followed	(j)						
	H		H	Hazardous waste disposal plan, if required							
-	H		H	Spill reporting procedures followed	(1) (m) (1)						
_		1	H	See Comment # 37 Preparedness, Prevention and Contingency Plan approved and implemented	(m) (1)						
	1	1	H	Special requirements followed for international shipments	(m) (5)						
	H	1	1	ON THE JOB OR CLASSROOM PERSONNEL TRAINING	9(1)(						
	1	H	H	PROGRAM AS PER 75.265 (F).	3(2)(-)						
			H								
		H	H	ì							
		Ц	$\sqcup$								
1	1	1		·							

# HAZARDOUS WASTE INSPECTION REPORT Part C - Comments

Company, Installation name The Theetric Materials Co.  County Exic Municipality North East  1. This follow up inspection was conducted to Check facility for compliance with all applicable requirements of Permit By Rule status and to insure that the suilations mentioned in a Notice of Violation dated fully, 1987 had been abouted.  2 Proper Pa. Negandous wester labels had been acquired.  3. A shipment of hazardous waste was made on Aug.  10, 1987. There was no hazardous waste heing street on site at the time of the inspection except a partially full containers of wheelabrator dust.  4. A plantic bood was being filled at the point of generation of a plantic bood was being filled at the point of generation at the point when sheet and the receiving container at the point where the hazardous wheelabrator dust was being generated. The container did must was being generated. The container did the print of about on it. This waste was being generated. The container did must have a hazar a hour in this report. Any violations which were uncovered during the inspection are indicated. Violations may also be discovered upon examination of the results of laboratory analyses and review of Department records. Notifications which were uncovered during the inspection are indicated. Violations may also be discovered upon examination of the coming, confirming any violations indicated herein and listing any additional violations.  Person Interviewed (signature)	Date of inspection 8-19-87 Identification number PAD 005 028642
County Eric Municipality North East  1. This follow-up inspection was conducted to check facility for compliance with all applicable requirements of Permit-By-Rule status and to insule that the reclations mentioned in a Notice of Violation dated July 1987 had been abouted,  2 Proper Pa. Hazardous wester labels had been acquired.  3. A shipment of lazardous wester was made on Aug.  10, 1987. There was no hazardous waster heing street on site at the time of the inspection tracept a partially full contained of wheelsheater dust which was being filled at the point of generation 4 a plantic bood was being used as a connector between the short and the reclaiming contained at the point where the hazardous which was being generated. This contained did not the short waste waste label on it me did to have a hazardous waste label on it. This contained so this inspection are should be properly labeled and the This inspection report is official notification that a representative of the Department of Environmental Resources, Burau of Solid Waste Management, inspected the above installation.  Containing softhis inspection are shown in this report. My violations wind the forther counts of laboratory analyses and review of Department records. Notification will be fortheroming, confirming any violations indicated herein and listing any additional violations.  Person Interviewed (signature)	il entre de la companya de la compa
This follow up inspection was conducted to  check failty for compliance with all applicable  requirements of Permit By Rule status and to  insue that the suclations mentioned in a Notice  of Violation doted July 1, 1987 his been about.  2 Proper To. Hazardene wester labels had been  arguild.  3. A shipment of hazardene wester was made on Aug.  10, 1987. There was no hazardene waste heiry  atored on site at the time of the inspection except  a partially full container of wheelships dust a dust.  Which was being filled at the point of generation.  4 a plastic hood was being used as a connected  between the shirst and the reclining container at  at the point where the hazardene valuations is the state on it. This  must have a hazardene waste label on it no  did it have an accumulation date on it. This  Container should be properly labeled and the  This impection report is official notification that a representative of the deportment of  Environmental Resources, Bureau of Solid Waste Management, inspected the above installation.  This inspection are indicated. Violations may also be discovered upon examination of the  results of laboratory analyses and review of Department records. Notification will be forth-  coming, confirming any violations indicated herein and listing any additional violations.  Person Interviewed (signature)	County Erie Municipality North East
check facility for compliance with all applicable requirements of Permit By Pule status and to insure that the reclations mentioned in a Notice if Violation dated July, 1987 his been abouted,  2 Proper Pa. Nazardous waste labels had been acquired.  3. A shipment of hazardous waste was made on Aug.  10, 1987. There was no hazardous waste heing atned on site at the time of the inspection except a partielle, full contained of wheelabrater dust  4. A plantic hood was blevel at the print of generation  4. A plantic hood was blevel at the print of generation  4. A plantic hood was blevel instance of wheelabrater  between the short and the reclining contained  at the print where the hazardous waste label on it not  died it have a hazardous waste label on it not  Contained a hazardous waste label on it. This  Contained should be projected labeled and the  This impocition report is official notification that a sepreculative of the Department of Environmental Resources, Bureau of Solid Naste Management, inspected the above installation.  This impocition are indicated. Violations may also be discovered the above installation.  This impocition are indicated. Violations may also be discovered upon examination of the results of laboratory analyses and review of Department records. Notification will be forth- coming, confirming any violations indicated herein and listing any additional violations.  Person Interviewed (signature)	
requirements of Permit By Rule status and to insure that the recolations mentioned in a Notice of Violation dated July 1, 1987 his been abouted, I Pripe. Pa. Nazardous waste bales had been acquired.  3. A shipment of hazardous waste was made on Aug. 10, 1987. There was no hazardous waste heavy stored on site at the time of the inspection except a partielly full container of wheelabrator dust. which was being filled at the print of generation 4 a plastic bood was being filled at the print of generation 4 at plastic bood was being used as a connector between the short and the receiving container at the point where the hazardous wheelabrator dust have a hazardous waste label on it me and it have a hazardous waste label on it. This container should be proposed labeled and the This inspection report is official notification that a seprecentative of the beoper ment of Environmental Resources, Bureau of Solid Naste Management, inspected the above installation. This inspection are shown in this report. Any violations which were uncovered during the inspection are shown in this report. Any violations which were uncovered during the inspection are shown in this report. Any violations which were uncovered during the inspection are indicated. Violations may also be discovered upon examination of the results of laboratory analyses and review of Department records. Notification will be forthered in the first person interviewed (signature)  Person Interviewed (signature)	
insule that the violations mentioned in a Notice of Violation dated July 1987 had been abouted,  2 Proper Pa. Nazardone waste baleds had been acquired.  3. A shipment of hazardone waste was make on Aug.  10, 1987. There was no hazardone waste heing street on aite at the time of the inspection except a partially full container of wheelabrator dust.  Which was being filler at the point of generation 4 a plastic bood was being filler at the point of generation between the short and the receiving container.  4 a plastic bood was being used as a connector between the short and the receiving container at the point where the hazardone wheelabrator dust was being generated. This container did must have a huga deep waste baled on it me date it have a huga deep waste baled on it. This container should be properly be above installation.  This inspection report is official notification that a expresentative of the Department of Environmental Resources, Bureau of Solid Naste Management, inspected the above installation.  Container should be properly labeled and the Diviolations which were uncovered during the inspection are shown in this report. Any violations which were uncovered during the inspection are indicated. Violations may also be discovered upon commination of the results of laboratory analyses and review of Department records. Notification will be forther coming, confirming any violations indicated herein and listing any additional violations.  Person Interviewed (signature)	requirements of Permit - By - Rule status and to
If Violation do ted July 1, 1987 had been aboted,  2 Proper Pa. Hazardone waste labels had been  acquired.  3. a shipment of hazardone waste was made on Aug.  10, 1987. These was no hazardone waste heing streed on site at the time of the inspection except a partially full container of wheelabrator dust.  which was being filled at the point of generation 4 a plantic bood was being used as a connector between the short and the reclining container at the point where the hazardone wheelabrator dust was being generated. This container did not the most base a hazardone waste label on it must have a hazardone waste label on it. This inspection report is official notification that a representative of the Department of Environmental Resources, Bureau of Solid Waste Management, inspected the above installation. The findings of this inspection are shown in this report. Any violations which were uncovered during the inspection are indicated. Violations was also be discovered upon examination of the results of laboratory analyses and review of Department records. Notification will be forthered to confirming any violations indicated herein and listing any additional violations.  Person Interviewed (signature)	
2 Proper To. Nazadowe waste babels had been  acquied.  3. A shipment of hazardow waste was made on Aug  10, 1987. There was no hazardows waste being  atred on site at the time of the inspection except a partielly full contained of wheelsbrater dust.  which was being filler at the point of generation  4. A plastic hood was being used as a connector  between the shirt and the reclining contained  at the point where the hazardow wheelsbrater  dust was being generated. This contained did  must have a hazardows waste label on it no  did it have an accumulation date on it. This  Container should be properly labeled and the This impection report is official notification that a spresentative of the Department of Environmental Resources, Bureau of Solid Waste Management, inspected the above installation.  The findings of this inspection are shown in this report. May violations which were uncovered during the inspection are indicated. Violations may also be discovered upon examination of the results of laboratory analyses and review of Department records. Notification will be forth- coming, confirming any violations indicated herein and listing any additional violations.  Person Interviewed (signature)	if Violation dated July 1, 1987 had been abouted.
a shipment of hospitans waste was made on Aug  10, 1987. There was no hospitans waste hing  stored on site at the time of the inspection except  a partially full container of wheelabrator dust.  which was being filled at the point of generation  4 a plastic bood was being used as a connection  between the shirt and the receiving container  at the point where the hazardous wheelabrator  dust was being generated. This container did  must have a hazardous waste label on it me  did it have an accumulation date on it. This  Container should be properly labeled and the  This inspection report is official notification that a representative of the Department of  Environmental resources, Bureau of Solid Waste Management, inspected the above installation.  The findings of this inspection are shown in this report. May violations which were uncovered during the inspection are indicated. Violations may also be discovered upon examination of the results of laboratory analyses and review of Department records. Notification will be forth-  coming, confirming any violations indicated herein and listing any additional violations.  Person Interviewed (signature)  Date	
3. A shipment of hazardous waste was made on Aug  10, 1987. These was no hazardous waste heing  stood on site at the time of the inspection except  a partially, full contained of wheelabrator dust.  which was being filled at the point of generation  4 a plastic hood was being used as a connected  between the shirt and the reclining contained  at the point where the hazardous wheelabrator  dust was being generated. This contained did  mot have a hazardous waste label on it. no  did it have an accumulation date on it. This  Container should be properly labeled and the This inspection report is official notification that a representative of the Department of Environmental Resources, Bureau of Solid Waste Management, inspected the above installation.  The findings of this inspection are shown in this report. Any violations which were uncovered during the inspection are indicated. Violations may also be discovered upon examination of the results of laboratory analyses and review of Department records. Notification will be forth- coming, confirming any violations indicated herein and listing any additional violations.  Person Interviewed (signature)  Date	·
stored on site at the time of the inspection iscept a partially full container of wheelabrator dust.  which was being filler at the point of generation of a plantic hood was being used as a connector between the short and the reclining container at the point where the hazardous wheelabrator dust was being generated. This container did not it have a hazardous waste label on it must have a hazardous waste label on it. This container of Environmental Resources, Bureau of Solid Waste Management, inspected the above installation. The findings of this inspection are shown in this report. Any violations which were uncovered during the inspection are indicated. Violations may also be discovered upon examination of the regults of laboratory analyses and review of Department records. Notification will be forthcoming, confirming any violations indicated herein and listing any additional violations.  Person Interviewed (signature)  Date	
a partielly full container of wheelabrater dust.  which was being filler at the point of generation.  4 a plastic hood was being used as a connector  between the short and the receiving container.  at the point where the hazardous wheelabrater  dust was being generated. This container did  must have a hazardous waste label on it me  did it have an accumulation date on it. This  Container should be properly labeled and the  Environmental Resources, Bureau of Solid Waste Management, inspected the above installation.  The findings of this inspection are shown in this report. Any violations which were uncovered during the inspection are indicated. Violations may also be discovered upon examination of the results of laboratory analyses and review of Department records. Notification will be forth-  coming, confirming any violations indicated herein and listing any additional violations.  Person Interviewed (signature)  Date	
a partially full container of wheelabrator dust which was being filled at the point of generation 4 a plantic hood was being used as a connector between the sheet and the receiving container at the point where the hazardous wheelabrator dust was being generated. This container did that have a hazardous waste label on it me did it have an accumulation date on it. This container did the property labeled and the This inspection report is official notification that a representative of the Department of Environmental Resources, Bureau of Solid Waste Management, inspected the above installation. The findings of this inspection are shown in this report. Any violations which were uncovered during the inspection are indicated. Violations may also be discovered upon examination of the results of laboratory analyses and review of Department records. Notification will be forthcoming, confirming any violations indicated herein and listing any additional violations.  Person Interviewed (signature)  Date	stored on site at the time of the inspection except
between the sheet and the receiving Container at the point where the hazardous wheelabrator at the point where the hazardous wheelabrator dest was being generated. This container did not the have a hazardous waste label on it must have a hazardous waste label on it. This inspection report is official notification that a representative of the Department of Environmental Resources, Bureau of Solid Waste Management, inspected the above installation. The findings of this inspection are shown in this report. My violations which were uncovered during the inspection are indicated. Violations may also be discovered upon examination of the results of laboratory analyses and review of Department records. Notification will be forthcoming, confirming any violations indicated herein and listing any additional violations.  Person Interviewed (signature)  Date	a partiella bull container if wheelabrator dust.
between the sheet and the receiving Container at the point where the hazardous wheelabrator at the point where the hazardous wheelabrator dest was being generated. This container did not the have a hazardous waste label on it must have a hazardous waste label on it. This inspection report is official notification that a representative of the Department of Environmental Resources, Bureau of Solid Waste Management, inspected the above installation. The findings of this inspection are shown in this report. My violations which were uncovered during the inspection are indicated. Violations may also be discovered upon examination of the results of laboratory analyses and review of Department records. Notification will be forthcoming, confirming any violations indicated herein and listing any additional violations.  Person Interviewed (signature)  Date	which was being filled at the point of generation
between the shirt and the receiving contained at the point where the hazardous wheelabrator dust was being generated. This contained distance what have a hazardous waste label on it me dist it have an accumulation date on it. This inspection report is official notification that a representative of the Department of Environmental Resources, Bureau of Solid Waste Management, inspected the above installation. The findings of this inspection are shown in this report. Any violations which were uncovered during the inspection are indicated. Violations may also be discovered upon examination of the results of laboratory analyses and review of Department records. Notification will be forthcoming, confirming any violations indicated herein and listing any additional violations.  Person Interviewed (signature)  Date	4. a plastic hood was being used as a connector
at the point where the hazardous wheelabrator dust was being generated. This container did  mat have a hazardous waste label on it me did it have an accumulation date on it. This  Container should be properly labeled and the the this inspection report is official notification that a representative of the Department of Environmental Resources, Bureau of Solid Waste Management, inspected the above installation. The findings of this inspection are shown in this report. Any violations which were uncovered during the inspection are indicated. Violations may also be discovered upon examination of the results of laboratory analyses and review of Department records. Notification will be forthcoming, confirming any violations indicated herein and listing any additional violations.  Person Interviewed (signature)  Date	
dust was being generated. This container did  sent have a hape done waste label on it me  did it have an accumulation date on it. This  Container should be properly labeled and the  This inspection report is official notification that a representative of the Department of  Environmental Resources, Bureau of Solid Waste Management, inspected the above installation.  The findings of this inspection are shown in this report. Any violations which were uncovered during the inspection are indicated. Violations may also be discovered upon examination of the results of laboratory analyses and review of Department records. Notification will be forth-  coming, confirming any violations indicated herein and listing any additional violations.  Person Interviewed (signature)  Date	
Container should be properly labeled and the This inspection report is official notification that a representative of the Department of Environmental Resources, Bureau of Solid Naste Management, inspected the above installation. The findings of this inspection are shown in this report. Any violations which were uncovered during the inspection are indicated. Violations may also be discovered upon examination of the results of laboratory analyses and review of Department records. Notification will be forthcoming, confirming any violations indicated herein and listing any additional violations.  Person Interviewed (signature)  Date	
Container should be properly labeled and the This inspection report is official notification that a representative of the Department of Environmental Resources, Bureau of Solid Waste Management, inspected the above installation. The findings of this inspection are shown in this report. Any violations which were uncovered during the inspection are indicated. Violations may also be discovered upon examination of the results of laboratory analyses and review of Department records. Notification will be fortheroming, confirming any violations indicated herein and listing any additional violations.  Person Interviewed (signature)  Date	
This inspection report is official notification that a representative of the Department of Environmental Resources, Bureau of Solid Waste Management, inspected the above installation. The findings of this inspection are shown in this report. Any violations which were uncovered during the inspection are indicated. Violations may also be discovered upon examination of the results of laboratory analyses and review of Department records. Notification will be forthcoming, confirming any violations indicated herein and listing any additional violations.  Person Interviewed (signature)  Date  Date	
This inspection report is official notification that a representative of the Department of Environmental Resources, Bureau of Solid Waste Management, inspected the above installation. The findings of this inspection are shown in this report. Any violations which were uncovered during the inspection are indicated. Violations may also be discovered upon examination of the results of laboratory analyses and review of Department records. Notification will be forthcoming, confirming any violations indicated herein and listing any additional violations.  Person Interviewed (signature)  Date  Date	
1.000.	This inspection report is official notification that a representative of the Department of Environmental Resources, Bureau of Solid Waste Management, inspected the above installation. The findings of this inspection are shown in this report. Any violations which were uncovered during the inspection are indicated. Violations may also be discovered upon examination of the results of laboratory analyses and review of Department records. Notification will be forth-
	Person Interviewed (signature) Date
Inspector (signature) Kichard & Stiaum Date 8-20-87	Inspector (signature) Richard E. Stiaum Date 8-20-87

# HAZARDOUS WASTE INSPECTION REPORT Part C - Comments

Date of inspection 8-19-87 Identification number PAD005028642
Company, Installation name The Electric Materials Co
County Frie Municipality North East
- accumulation date is the first date any hazardous
waste is placed in the container.
5 Records are now being maintained which would
reflect the quantities of the wastewaters from the
electroplating operations which contain eyamile
that are being batch treated in a 1000 gallon
betch treatment tout It was recommended
that these quantities be reported on the
Quarterly Reports as well as on the annual Report.
6. an analysia of the rinse waters from the Old Platering
Room which are being discharged directly to the
POTW which are being discharged directly to the
On analysis of these waters should be sent to
this office within fifteen (5) days of the receipt
of this report. Mr. Wiles stated that the
analysis was available but requested some
time to locate it.
I Since this facility has undergone sweet
changes since the PPC Plan was made in
This inspection report is official notification that a representative of the Department of Environmental Resources, Bureau of Solid Waste Management, inspected the above installation. The findings of this inspection are shown in this report. Any violations which were uncovered during the inspection are indicated. Violations may also be discovered upon examination of the results of laboratory analyses and review of Department records. Notification will be forthcoming, confirming any violations indicated herein and listing any additional violations.
Person Interviewed (signature) Date
Inspector (signature) Kichaul E Straun Date 8-20-87

	Date of inspection 8-19-87 Identification number F17 D005028642
	company, Installation name The Fleetric Materials Co.
	county. Erie. Municipality North East
	Movember 1984, it was agreed during the inspection
	that a new PPC Plan would be made reflection
SIAL *	all the changes and be submitted to this affice
	by Mar 2, 1987. Particular attention should be
	paid to how the wastewaters from the electroplate.
	appeations which contain examile are handlad.
<u>}</u>	han then point at micination to their 1-1
	from their point of origination to their finel disposition. An effective PPC Plan in required
	under 75.265 (2)(17).
	8. The pit / sump located under under the cyanile
	tank was being used as a containment tank.
	This practice should close. The overflow
	wastewater which enter this pit/ sump shalo
	be immobiately pumped out, thus allowing
	this pit / sump to function as an emergence,
1	continuent for the above tanks.
6	9. The wastiwaters from the above mentional sums are
	being pumped to a 2500 gallon underfloor sump
	take who the and Pald Del Deine bumbel
	This inspection report is official notification that a representative of the Department of
	Environmental Resources, Bureau of Solid Waste Management, inspected the above installation. The findings of this inspection are shown in this report. Any violations which were uncovered
	during the inspection are indicated. Violations may also be discovered upon examination of the results of laboratory analyses and review of Department records. Notification will be forth-coming, confirming any violations indicated herein and listing any additional violations.
:-	
	2111-01
	Inspector (signature) Richard C. Shawn Date 8-20-87

## HAZARDOUS WASTE INSPECTION REPORT

Part C - Comments
Date of inspection 8-19-87 Identification number PAD 005028642
Company, Installation name The Electric Materials Co
County. Erie. Municipality North East
into a 1000 gallon batch treatment tank. Since
that is always a certain inherent danger associated
with underground tanks it is recommended that
The Electric Materials Co explore other eptimis
concerning the storage of these waster. By
storing using this tank the Electric Materials &
may have other responsibilities under the
LUST (Leahing Underground Storage Tank)
requirements: For information concerning this
program contact:
MR. Foster Diodata
Pa. Dept. of Enviro Resources
Bureau of Water Quality
P.O. Box 2063
Fulton Bank Bldg.
Harrisburg PA 17/20
717-447-8184
Until another method is employed to & store
there wastewaters some method should be employed
This inspection report is official notification that a representative of the Department of
Environmental Resources, Bureau of Solid Waste Management, inspected the above installation. The findings of this inspection are shown in this report. Any violations which were uncovered
during the inspection are indicated. Violations may also be discovered upon examination of the
results of laboratory analyses and review of Department records. Notification will be forth-coming, confirming any violations indicated herein and listing any additional violations.
Person Interviewed (signature) Date
Inspector (signature) Richard & Steam Date 8-24-87

# HAZARDOUS WASTE INSPECTION REPORT . Part C - Comments

180 F.

Date of inspection 8-19-87 Identification number PAD 005028642
company, Installation name The Electric Materials Co
county Erie Municipality North East
which would make it possible to accurately
determine the valume of wastewater which
is present in this tank at any given time
This should be accomplished by Mar. 2, 1987
as agreed to during the inspection.
also, please dominent in writing and submit
receipt of this letter all available information
concerning this 2500 callon tunk . Please
include such information as actual dimensions,
construction material living material (and
the heers) and age.
This inspection report is official notification that a representative of the Department of Environmental Resources, Bureau of Solid Waste Management, inspected the above installation. The findings of this inspection are shown in this report. Any violations which were uncovered during the inspection are indicated. Violations may also be discovered upon examination of the results of laboratory analyses and review of Department records. Notification will be forthcoming, confirming any violations indicated herein and listing any additional violations.
Person Interviewed (signature) Date
Inspector (signature) Richard E. Stisum Date 8-24-87



#### UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

#### **REGION III**

841 Chestnut Building Philadelphia, Pennsylvania 19107

SUBJECT: RCRA Inspection - THE ELECTRIC MATERIALS CO.
PAD 00 502 8642

DATE: JULY 27, 1987

FROM:

William L. Walsh, EPS

PA RCRA Enforcement Section (3HW11) WCW

TO:

File

Peter W. Schaul, (hi

PA RCRA Enforcement tion (3HW11)

THE STATE IS TAKING ACTION TO RESOLVE THE VIOLATIONS IN THIS INSPECTION REPORT.

WE WILL MONITOR THE STATE ACTIVITY REGARDING RESOLUTION OF THESE VIOLATIONS.

Waste mislabeling on Funstes

bc: EPA 🗸

Central Office

Meadville Regional Office

Erie County File

John Mead

Chron.

1012 Water Street

Meadville, Pennsylvania 16335

Telephone: A. C. 814/724-8526

July 1, 1987

#### CERTIFIED MAIL #P-547 805 048

Subject: Hazardous Waste Inspection

The Electric Materials Company

ID #PAD005028642

NOTICE OF VIOLATION

Mr. John Wilcox, Safety Director The Electric Materials Company 50 South Washington Street North East, Pennsylvania 16428

Dear Mr. Wilcox

This Notice of Violation is being sent to you pursuant to the Pennsylvania Solid Waste Management Act, the Act of July 7, 1980, P.L. 380, No. 97, 35 P.S. 6018.101 et seq. The requirements of this Act are being enforced by the Pennsylvania Department of Environmental Resources which is responsible for the regulating and managing of solid waste, including hazardous waste, within the Commonwealth of Pennsylvania. Your facility is in violation of the above mentioned Solid Waste Management Act and of the Chapter 75 Hazardous Waste Regulations adopted on September 14, 1985 (25 Pa. Code 75.1 et seq.).

Department personnel performed a hazardous waste generator inspection of The Electric Materials Company's facility located at 50 South Washington Street, North East, Pennsylvania on June 17, 1987. This inspection revealed the following violations:

> Wastewater from the cadmium, silver and copper electroplating operations which contain cyanide wastes are discharged to a 2,500 gallon underfloor sump tank. The accumulated wastewater is then pumped into a 1,000 gallon treatment tank for batch treatment. Records were not available which would indicate the quantities of hazardous waste generated during the electroplating process and treated under Permit-by-Rule status. This is unlawful conduct as defined by Section 403(b) which states:

"It shall be unlawful for any person or municipality who generates, transports, stores, treats or disposes of hazardous waste to fail to maintain such records as are necessary to accurately identify the quantities of hazardous waste generated, the constituents thereof which are significant in quantity or in potential harm to human health or the environment, the method of transportation and disposition of such waste; and where applicable, the source and delivery points of such hazardous waste.".

- 2. Six (6) containers of hazardous waste were labeled as hazardous waste but proper Pennsylvania hazardous waste labels were not being used as required by Section 75.262(f)(1)(iii).
- 3. One (1) container of hazardous waste labeled as wheelabrator dust had been stored in excess of ninety (90) days in violation of Section 75.262(g)(1)(i).
- 4. One (1) container of hazardous waste (wheelabrator dust) was not closed in violation of Section 75.265(q)(3) which generators are referred to by Section 75.262(g)(1)(iii).

In order to abate the above mentioned violations, The Electric Materials Company should:

- Conform to Section 264(k) which requires that an operating record be maintained at the facility which would reflect the quantities of hazardous waste generated and treated.
- 2. Obtain and use proper Pennsylvania hazardous waste labels.
- 3. Ensure that all hazardous waste is either treated or shipped within ninety (90) days.
- 4. Ensure that all containers holding hazardous waste are kept closed during storage, except when it is necessary to add or remove waste.

Please be advised that the Solid Waste Management Act provides for separate penalties for violations of each of its sections on separate days.

This Notice does not waive, either expressly or by implication, the power or authority of the Commonwealth of Pennsylvania to prosecute for any and all violations of its law arising prior to or after the issuance of this Notice or the conditions upon which this Notice is based.

This Notice shall not be construed so as to waive or impair any rights of the Department of Environmental Resources heretofore or hereafter existing. This Notice shall also not be construed as a final action of the Department of Environmental Resources.

Should you have any questions regarding this Notice, please feel free to contact me at this office.

Sincerely,

Richard E. Strawn

Solid Waste Specialist Bureau of Waste Management

Richard E. Strawn

RES/skg

or those officers.

#### HAZARDOUS WASTE INSPECTION KILLONG CONOTATORS ~ FAIT A

# EPA

Date of Inspection 6-17-87 Time start 10:15 Time finish 2:3
Name of inspector Richard Strawn, Ricardo Grison
Company, installation name The Electric Materials Co.
socation 50 South Washington St. North Fast PA 11428
county Erie Municipality North East
Identification number PAD 005 028 642
Name of responsible official John Wilcox
ritle Safety Director
Mailing address 50 South Washington St, North Fast PA 1642
Area code and phone no. 814-725-9621
Nume of person interviewed John Wilcox
ritle Safety Director
Mailing address (if different from above) 146000
trea code and phone no. Above
•
1. Current waste handling method: Permit by-Rule
a. A On-site A treatment C storage, C disposal
b On-site _ use, _ reuse, _ recycle, _ reclaim
c. Ø Off-site / troatment, / storage, Ø disposal
d. Ø Off-site Duse, Dreuse, Ø recycle, Dreclain
2. Amount of hazardous waste produced:  Bound waste last two produces.
Based upon Last Inspection Report.  Not determined how much waste
bkg. Ar. water is being treated.
. Types of hazardous waste produced by Hazardous Waste Number:
FOOT, FOOL, FOOT, DOOR, DOOK, DOOR
Are harardous wastes transported off-site by the generator? [] Yes [] No

•				1. 4 19-17-11-1. 1 . 7 . 4 to 1 . 1 . 1 . 1 . 1 . 1 . 1 . 1 . 1 . 1	-
	100 mg 1 m				t
	V	1	-	Identification number	100
	V			Hazardous waste shipments offered only to licensed transporters	(c) 6
	V			Authorization received from TSD facility for wastes shipped off-site	(á,
		1		17. manifest used for intrastate chipments	(4.)
	1			Disposer state manifest or EPA format manifest used for out-of-state shipments	c) (:
	V			Manifests filled out properly and completely	(c) (7
	1		<u> </u>	Manifests routed properly and within time limits (24 hours)	(L)
	V			Proper U.S. DOT shipping containers or packages	<b>(f</b> ) (
	1			Shipping containers marked and labeled according to U.S. DOT	f)(1).
X				Containers of 100 gal. or less marked with required PA label	f) (i) (
			1	Placards offered to transporter	(f) (i)
X				Wastes accumulated on-site for less than 90 days	(g) (1)
X				Wastes stored in proper containers and properly marked and labeled	(g) (1)
$\bigvee$				Containers managed in accordance with $.75.265(q)(1-9)$	(g) (i)
	1			Containers clearly marked with accumulation date and visible for inspection	(g)(1)
	1			Records retained at designated location for 20 years	(h)
	1			Quarterly reports submitted to the Department	(i)
		2		Exception reporting procedures followed	(5)
		ب		Hazardous waste disposal plan, if required	(1)
		1		Spill reporting procedures followed	(m) (l)
	1			Preparedness, Prevention and Contingency Plan approved and implemented	(m) (5)
		1		Special requirements followed for international shipments	(0)
	1			PRUGRAM AS PER 75.265 (F).	9(1)(
				·	

Part C - Comments
Date of inspection 6-17.57 Identification number 711005025642
Company, Installation name the Hectric Materials Co.
county File Municipality North Fast
1. Il Election Materiala Company has motified they
we trinting hagardous waste at their facility
under Permit - by - Rich status. This importion
was to confine compliance with the Permit - by-
Rule requirements. This facility reeds to
develop and follow a written inspection
solicitale as required in Dection 25. 264(e)(2)
The facility had treated wastemater from
electropolating operations which contained oganide.
a record of the quantities of enancies wastewater
treated was not available. A record of the
quantities of lagar love wanter treated are to the
maintained in accordaines with Bution 15. 164 (K).
all other required records were being maintained.
annual report farms will be sont by the Department
2. Dioring the inspection it was observed that a small
quantity of non hazardour wheelaheator dust
had been duringed outer a pile of foundry sand.
This inspection report is official notification that a representative of the Department of Environmental Resources, Bureau of Solid Waste Management, inspected the above installation. The findings of this inspection are shown in this report. Any violations which were uncovered during the inspection are indicated. Violations may also be discovered upon examination of the results of laboratory analyses and review of Department records. Notification will be forthcoming, confirming any violations indicated herein and listing any additional violations.
Person Interviewed (signature)Date
Inspector (signature) A. Jain & Stains Date 6-19-82

Date of inspection 612-87 Identification number PAN COSC 25642
Company, Installation name The Electric Materials Co
County Eries Municipality North East
The amount of which about on their would amount to
approximately fifty for gallones. an annal
analysis of the foundry sand waste horse
her submitted to the affice by May 19, 1987
as a condition of the Module I approval at
Lakewiew Fredfill. a of the date of the report
no analyses has been received at their office.
In addition please be advised that the
wheelabrates dut (non-hazardous) is
presently going through the Module I review
process to be disposed of at La housen Jamblill
but as of their date has not locar approved
therefore since the min- hazardour whechabiate
dust and the family raid have been micked
together mous af the material brown this vile
should be desposed of at Labourer-Landfill
until both of their waster have been
approved and have satisfied all conditioned
This inspection report is official notification that a representative of the Department of Environmental Resources, Bureau of Solid Waste Management, inspected the above installation. The findings of this inspection are shown in this report. Any violations which were uncovered during the inspection are indicated. Violations may also be discovered upon examination of the results of laboratory analyses and review of Department records. Notification will be forthcoming, confirming any violations indicated herein and listing any additional violations.
Person Interviewed (signature) Date
Inspector (signature) Richard E. Sliman Date 219-87

Part C - Comments
Date of inspection 6-79 89 Identification number PAD 005028642
Company, Installation name The Electric, M. terials Co
County 1116 Municipality Naith Fast
of that approval.
- 30 div containers of hazardone waste were met
labeled with the proper Re hazardone innetes
- Caled. The Electure Material's Company should
acquire proper la hazardone n'este labels
which meet the requirements set fact in
Section 35, 362 (1) (ili).
4. One container of wheelatiator dust (poox) had
been stored in electer of mineter days in
violation of Section 750 262 (g) (i)
5. One container of hazardous was to (wheel aluston
dust ) was not closed in ridation of Section
15. 265 (g) (3) which generators are referred to
by 3 retin 23. 26.2(g)() (iii)
les Manifests and Quartolly Reports for 1986 and
fruit quarter of 1482 were the chool during the
inshiction.
Le a follow up weeperhein will be conducted in the
near future.
This inspection report is official notification that a representative of the Department of Environmental Resources, Bureau of Solid Waste Management, inspected the above installation. The findings of this inspection are shown in this report. Any violations which were uncovered during the inspection are indicated. Violations may also be discovered upon examination of the results of laboratory analyses and review of Department records. Notification will be forth-coming, confirming any violations indicated herein and listing any additional violations.
Person Interviewed (signature) Date
Inspector (signature) Richard E Strawn Date 1.19-87

## Hazardous Waste Quantity Notification

Business Name The Electric Materials	<u>C</u> 0
Business Address 50 South Washington St	
North East, Pa. 16428	
EPA ID Number PAD 00 502 8642	
Hazardous Waste Generated	
0 - 100 kg/month //	
100 - 1000 kg/month	
1000 kg/month or more //	

Jahn Milen Sapety Divector

Sugnature and Title Waste worma; er



Official Business Penalty for Private Use \$300 FIRST-CLASS MAIL POSTAGE & FEES PAID EPA PERMIT NO. G-35

United States Environmental Protection Agency Washington DC 20460

JOHN A ARMSTEAD VA/WV SECTION (3HW31) US EPA REGIONIII 841 CHESTNUT ST. PHILADELPHIA, PA 19107

EPA Form 5180-11 (5-79)

ŧ

BUREAU OF SOLID WASTE MANAGEMENT
NOTIFICATION OF HAZARDOUS WASTE ACTIVITY

	MOTH ICATION OF	11/12/11/2				_ ~		
INSTALLATION'S EPA I.D. NUMBER	down the second		A House			A STATE OF THE STA	CANAL	
PAD00502864121								
NAME OF INSTALLATION			West in		24.5	的图式的	道的	A STATE OF THE STA
The 1	Electric Mater	ials C	ompany	y				
II INSTALLATION MAILING ADDRESS	AND			3 10 10	A STOCK OF		mr. Ca	
STREET	OR P. O. BOX							
P 0	Box 390							
CIT	Y OR TOWN						т.	ZIP CODE
Nortl	n East ·					P	A	16428
IV LOCATION OF INSTALLATION	Telling of the second	THE PARTY OF THE P	14623		0.000	Felial Street	185	VALOUAL MANAGEMENT
	OR ROUTE NUMBER			340000		MUN	VICIP/	LITY
50 South Wash	nington Street					North	Eas	st
<del></del>	Y OR TOWN		т.	ZIP CODE			COUN	
North East		P	A 16	5428			Erie	2
V INSTALLATION CONTACT;	Savara reserv	TO MAKE HIS TO					7110	TOTAL STATE OF THE
	ID TITLE ilast, first, & jo	b title)			(P) was a constraint		PHON	E NO. fares code & no.)
Wilcox, John	Safety Dir	ector				8	1 4	7 2 5 9 6 2 1
	MANAGED BY MITTERS		17/2014			THE SE	1 3 7 2	THE PROPERTY OF THE PARTY OF TH
	A. NAME OF	THE PERSON NAMED IN	ION'S LEG	SAL OWNE	R			
The Electric	Materials Com	nany						ر کرد 20 ا
B. TYPE OF OWNERSHIP Corpora		-F				<del></del>		
(enter the appropriate letter into box)	48-25, 43					•		
F - FEDERAL M - NON-FEDERAL	M			⁴.				
(1) 010 00055 (4 ) (1)		Hansham Mills	TO STATE OF THE	think with	Total visitable	essanaan	(Prode	
/II SIC CODES (4-digit in order of priority)	IRST		e l'allere d'	diam't his		HIRD	27.6	
1 1 1 1/2 200	inoi	- <del></del>		specify)		, עאוה		<u> </u>
33 31	COND				33 62	OURTH		
[specify] 36 29	COND	<del> -</del>		specify)		OUNTH		
/III TYPE OF HAZARDOUS WASTE ACTI	VITY	signal across the state of	<u>,                                    </u>		NEW YORK	CIE (SUA)	and the	
	TORE		SPORTA					CYCLE, RECLAIM
	and the second s	1 1	PLETE IT		اللا	G. REUS	4. KE	Trees, necessing
B. TREAT	DISPOSE	** F. PERM	IT BY RU	LE		H. OTHE		
IX MODE OF TRANSPORTATION (transp	orters only)		CARDON PO	MODELL SY	的特別學	en Chic	A 3.44	A CONTRACTOR OF THE PARTY OF TH
A. AIR A B. RAIL	C HIGHWAY	J.D. WATE			R (specify)			
X EXISTING ENVIRONMENTAL PR		-			STONE STONE	CONTRACTOR IN	<b>A.</b>	A SECULAR DE LA CONTRACTION DEL CONTRACTION DE LA CONTRACTION DE L
A. NPDES (Discharges to Surface Water)	D. PSD (Air Emissia	ns from Prop	osod Sour	ma wa				nagement Permit
								Die Machine
B. UIC (Underground Injection of Fluids)	E. S	OLID WAST	Ę					3-00017, Sand 5-313-0018
	11 1 1 1 1 1 1			1 1	ast, ca	Dinec	11-4-	)-313-0010
· C. RCRA (Hazardous Wastes)	F.	OTHER		ta esta s	(specif	γj		
1 TYPE OF NOTIFICATION	1000					2000年	35 TV	VALUE VAN DE VAN
11. TYPE OF NOTIFICATION,	1111-1111	To palant Ana	Alta is la relief de	Sept. Com			WYPE C	erification of a channel
Mark "X" in appropriate box to indica general information, hazardous waste handl JIONS).								
XX A. FIRST NOTIFICATION	C. DEL							OF AN ACTIVITY

particular and an analysis in a construction of the construction o	(man front)	All Control of the Co								
A. HAZARDOUS WASTES FROM NON-SPECIFIC SOURCES. Enter the four-digit number from \$75.261(h)(2) for each listed hezardous waste										
from non-specific sources your installation handles. Use additional sheets if necessary.										
1 2	3 4	5	6							
7 8	9 10	11	12							
B. HAZARDOUS WASTES FROM: SPECIFIC SOURCES. Enter the four-digit number from \$75.261(h)(3) each listed hazardous waste from specific										
industrial sources your installation handles. Use additional shoots if necessary.										
13 14	15 16	17	18							
F 0 0 1										
19 20	21 22	23	24							
25 26	27 28	29	30							
C COMMERCIAL CHEMICAL PRODUCT HAZARDOUS W	ASTES. Enter the four-digit number	from \$75.261(h)(4) for each of	:homical substance							
your installation handles which may be a hazardous waste.	Use additional sheets if necessary									
. 31 32	33 34	35	36							
37 38	39 40	41	42							
43 44	45 46	47	48							
D. CHARACTERISTICS OF NON-LISTED HAZARDOUS W		sponding to the characteristics	of non-listed							
hazardous wastos your installation handles. (See: \$75.261(g	)(2) through (5))									
1. IGNITABLE 2. COF	RROSIVE 3. R	EACTIVE	4. EP TOXIC.							
XIII CERTIFICATION										
× -										
I certify under penalty of law that I have personal attached documents, and that based on my inquiry	lly examined and am familiar of those individuals immediate	with the information subm	nitted in this and all ing the information,							
I certify under penalty of law that I have persona attached documents, and that based on my inquiry I believe that the submitted information is true, a submitting false information, including the possibil	accurate, and complete. I am ility of fine and imprisonment	aware that there are sign	nificant penalties for							
SIGNATURE 2	NAME and OFFICIAL TITLE (7		DATE SIGNED							
Tiemes L'Aluxon	Vice President-Ge		3/30/83							
	Vice liesident-de	neral hanager								
FOR OFFICIAL USE ONLY										
			•							
			•							
<ul> <li>A supplied to the property of the</li></ul>										

Gen



# ACKNOWLEDGEMENT OF NOTIFICATION OF REGULATED WASTE ACTIVITY

(VERIFICATION)

This is to acknowledge that you have filed a Notification of Regulated Waste Activity for the installation located at the address shown in the box below to comply with Section 3010 of the Resource Conservation and Recovery Act (RCRA). Your EPA Identification Number for that installation appears in the box below. The EPA Identification Number must be included on all shipping manifests for transporting hazardous wastes; on all Annual Reports that generators of hazardous waste, and owners and operators of hazardous waste treatment, storage and disposal facilities must file with EPA; on all applications for a Federal Hazardous Waste Permit; and other hazardous waste management reports and documents required under Subtitle C of RCRA.

EPA I.D. NUMBER

PAD005028642

THE ELECTRIC MATERIALS CO 50 S WASHINGTON ST NORTH EAST , PA 16428 JOHN WILCOX MGR

INSTALLATION ADDRESS

50 S WASHINGTON ST NORTH EAST PA 16428

EPA Form 8700-12A (6-90)



#### ACKNOWLEDGEMENT OF NOTIFICATION OF HAZARDOUS WASTE ACTIVITY (VERIFICATION)

This is to acknowledge that you have filed a Notification of Hazardous Waste Activity for the installation located at the address shown in the box below to comply with Section 3010 of the Resource Conservation and Recovery Act (RCRA). Your EPA Identification Number for that installation appears in the box below. The EPA Identification Number must be included on all shipping manifests for transporting hazardous wastes; on all Annual Reports that generators of hazardous waste, and owners and operators of hazardous waste treatment, storage and disposal facilities must file with EPA; on all applications for a Federal Hazardous Waste Permit; and other hazardous waste management reports and documents required under Subtitle C of RCRA.

EPA I.D. NUMBER

PAD 00 502 8642

Electric Materials Co. P.O. Box 390 North East, PA 16428 Attn: John Wilcox, Safety Dir.

INSTALLATION ADDRESS

50 S. Washington Street North East, PA 16428

EPA Form 8700-12B (4-80)